

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining JOHN R BAZA Division Director

Inspection Report Minerals Regulatory Program

Date Submitted: 08/06/2013

	CORT			
Reviewed	Yen/			

Mine	e Name: Snow White	Permit Number:	M/049/0030	Permi	t Fees:	Paid	
Ope	rator Name: Interstate Brick Co.	Inspection Date:	08/06/2013	Bond	Amount:	\$143,300.00	
Insp	ector(s): A. Abate, J. Hewitt, F. Delliskave	Time:	10:30 AM	Bond	Escalation:	01/31/16	
Othe	ers:	Mine Status:	Active				
Elements of Inspection					Comment	Enforcement	
1.	Permits, Revisions, Transfer, Bonds						
2.	Public Safety (shafts, adits, trash, signs, highwalls)						
3.	Protection of Drainages/Erosion Control						
4.	Deleterious Material						
5.	5. Roads (maintenance, surfacing, dust control, safety)						
6.	Reclamation				V		
7.	Backfilling/Grading (trenches, pits, roads, highwalls, shafts)			V	V		
8.	Soils						
9.	Revegetation						
					-		

Purpose of Inspection

The Division accompanied the operator to the mine to discuss the contemporaneous of reclamation performed at the site.

Inspection Summary

The operator pointed out a berm area on the west side of the lower pit of the mine that had been reclaimed. The operator explained that reclamation was planned as the overburden from the mine highwall would be placed in front of the berm (to the east) and then seeded. The operator explained that there was no topsoil salvaged at this mine. We discussed using biosolids as a possible option to help enhance vegetation growth. The operator explained that there were some biosolids available for free from a dealer in the Orem area but it had landfill waste contained within it. From the sounds of it, this particular biosolid material would be undesirable to use at this site. Discussed other areas within the permit boundary that could be contemporaneously reclaimed. A large pile of material on the area on the north side of the lower pit was pointed out as an area that could be reclaimed (see photo). Another area was the south pit where active mining has been ongoing. There is a large flat area that was formerly used to stage clay product. The clay product is gone but the area could be reclaimed as it is a large flat surface that looks much like a parking lot. This area could be roughed and seeded as part of the contemporaneous reclamation plan.

Conclusions and Recommendations

In accordance with R647-4-107.6,	The operator sho	uld amend their	plan to add the a	reas discussed	during today's	s inspection as are	as planned
for contemporaneous reclamation.	11011	/					

Inspector's Signature:


CC: John Hewitt, Interstate Brick Co. - 9780 S 5200 W, West Jordan, UT 84088


 $File: \ /NRLOGMFS1/ogm/GROUPS/MINERALS/WP/M049-Utah/M0490030-SnowWhite/inspections/Insp-08062013.pdf$



Mine: M/049/0030 Inspected: 08/06/2013







Closer view of the overburden stockpile.



View of the south pit of the Snow White Mine. An ephemeral drainage cuts through as seen beyond the pinon/juniper trees. The flat area above represents an area where clay had been staged. This flat area should be reclaimed if no longer in use.

